MECHANICAL ENGINEERING: Triodyne Inc. (Est. 1969) Ralph L. Barnett Dolores Gildin Carl Uzgiris

> Mechanical Engineering Dennis B. Brickman Kenneth L. d'Entremont Michael A. Dilich Christopher W. Ferrone Suzanne A. Glowiak John M. Goebelbecker Crispin Hales Gary M. Hutter Brian D. King Dror Kopernik Woodrow Nelson Peter J. Poczynok R. Kevin Smith Harry R. Smith William G. Switalski Andrew H. Tudor James R. Wingfield

Library Services Lucinda Fuller Betty Bellows Marna Forbes Maureen Gilligan Jan A. King Norene Kramer Florence Lasky Neil Miller Denise Prokudowicz Jackie Schwartz Peter Warner

Information Products Expert Transcript Center (ETC) Marna Forbes Glenn Werne Contract Services Lucinda Fuller

Graphic Communications and Video Services Mary A. Misiewicz Charles D'Eccliss Robin Stone Christina Timmins Lynn Wallace-Mills Thomas E. Zabinski Training and Editorial Services

Paula L. Barnett Model Laboratory 2721 Alison Lane Wilmette, II 60091-2101 Robert Kaplan Bill Brown

Mario Visocnik Vehicle Laboratory Charles Sinkovits Patrick M. Brinckerhoff

Photographic Laboratory 7903 Beckwith Road Morton Grove, IL 60053 Larry Good

Business Systems Sharon L. Mathews Maryalyce Skree Julia Andrade Peggy Dietrich Sandra M. Duff Chris Ann Gonatas

Special Projects John K. Burge Michael F. Mulhall

FIRE AND EXPLOSION Triodyne Fire & Explosion Engineers, Inc. (Est. 1987) 2907 Butterfield Road Suite 120 Oak Brook, IL 60521-1176 (630) 573-7707 FAX: (630) 573-7731

Officers/Directors John A. Campbell Reed B. Varley Ralph L. Barnett . Carl Uzgiris

Chicago Office John A. Campbell Scott M. Howell Thomas H. Miller Kim R. Mniszewski

Miami Office 1110 Brickell Avenue Suite 430 Miami, FL 33131-3135 (305) 374-4009 FAX: (305) 374-4007 Reed B. Varley Sheila Faith-Barry



September 1996

Volume 4, No.4

Triodyne Inc. Consultants in Safety Philosophy and Technology 5950 West Touhy Avenue Niles, IL 60714-4610 (847) 677-4730 FAX: (847) 647-2047 e-mail: infoserv@triodyne.com

VEHICLE SAFETY

Is a Left Turn Right?

by John Goebelbecker, P.E.¹, Michael A. Dilich² and Dror Kopernik³

ABSTRACT

A heavy truck is about to turn left onto a high speed, multi-lane highway. An approaching car in the distance appears far enough away for the truck driver to pull out and start his turn. Seconds later, a collision occurs. What went wrong?

DISCUSSION

Compared to automobiles, heavy trucks require substantial time to enter a highway due to the truck's length and slow acceleration. The left turn maneuver from a driveway depicted in Figure 1 is especially difficult because the truck driver must coordinate the timing of a rather long and slow crossing with the approach of traffic from both directions. Frequently, cooperation from approaching traffic is required to permit the truck to complete this maneuver safely. When an accident occurs, a number of possible factors related to the vehicles, the drivers, and/or the highway must be investigated before the cause(s) of the accident can be determined or fault can be established.

The following list of possible contributing factors was developed as an aid to the investigation of such accidents.



Figure 1 - AIRMAP⁴ of left turn across multi-lane highway.

¹ Project Engineer, Triodyne Inc., Niles, IL.

² Principal Mechanical Engineer, Triodyne Inc., Niles, IL.

³ Senior Mechanical Engineer, Triodyne Inc., Niles, IL.

⁴ AIRMAP (Accident Investigation and Reconstruction Mapping with Aerial Photography) is a proprietary mapping system developed by Triodyne.

ENVIRONMENTAL ENGINEERING Triodyne Environmental Engineering, Inc. (Est. 1989)

5950 West Touhy Ave Niles, IL 60714-4610 (847) 647-6748 FAX: (847) 647-2047

Officers/Directors Gary M. Hutter Ralph L. Barnett S. Carl Uzgiris

Engineering/Science John P. Bederka, Jr Richard Gullickson Diane K. Moshman James T. O'Donnell William D. Sheridan Audrone M. Stake

Library/Research Services Lucinda Eulle Shelley Hamilton

RECREATION ENGINEERING Triodyne Recreation Engineering, Inc. (*Est. 1994*) 5950 West Touhy Avenue Niles, IL 60714-4610 (847) 647-9882

FAX: (847) 647-0785 Officers/Directors Brian D. King Jeffery W. Abendshien Ralph L. Barnett S. Carl Uzgiris

SAFETY RESEARCH Institute for Advanced Safety Studies (Est. 1984) 5950 West Touhy Avenue Niles, IL 60714-4610

(847) 647-1101

Chairman of the Board Ralph L. Barnet

Executive Director Leslie A. Savage

Director of Research James T. Semrau

Information Services Lucinda Eulle

Senior Science Advisor Theodore Libe

MANUFACTURING Alliance Tool & Mfg. Inc.

(Est. 1945) 91 East Wilcox Street Maywood, IL 60153-2397 (312) 261-1712 (708) 345-5444 FAX: (708) 345-4004

Officers Carl Uzgiris S. Carl Uzyma Ralph L. Barnett

General Manager Ramesh Gandhi

Plant Manager Rav Gach

Founders/Consultants Joseph Gansacz Albert Kanikula

CONSTRUCTION: Triodyne-Wangler Construction Company Inc.

(Est. 1993) 5950 West Touhy Avenue Niles, IL 60714-4610 (847) 647-8866 FAX: (847) 647-0785

Officers/Directors/Managers Joel I. Barnett William A. Wangler Joseph Wangler Ralph L. Barnett S. Carl Uzgiris

CONSULTANTS: Richard M. Bilof, Ph.D. Electromagnetic Compatability

R. A. Budenholzer, Ph.D. Power and Energy

Claudine P. Giebs, M.S Biomechanics David W. Levinson, Ph.D

Senior Metallurgical Advisor James T. O'Donnell, Pharm.D.

Pharmacology Steven R. Schmid, Ph.D. Food Processing Equipment



Figure 2 - AIRMAP of headlight glare impairment situation.

POSSIBLE CONTRIBUTING FACTORS

Driver Factors to Consider

- Truck driver did not look for approaching traffic before pulling into highway.
- Truck driver saw approaching traffic but pulled into highway anyway when approaching traffic was too close.
- □ Approaching driver was inattentive, looking elsewhere, preoccupied with personal problem, etc.
- Approaching driver travelled at excessive speed for conditions (weather, road surface, others) affecting truck driver's estimate of approaching vehicle arrival.
- Truck driver was impatient and did not wait a reasonable time for traffic to clear before proceeding into road.
- □ Traffic from right forced truck to slow down or stop before completing turn.
- Truck's headlights in median or opposite lane impaired approaching driver's ability to detect trailer ahead. (See Figure 2)
- □ Truck driver failed to compensate for line-of-sight visibility obstruction such as foliage, building, or sign.
- Approaching driver failed to compensate for line-ofsight visibility obstruction such as hill crest or sharp curve.
- Driver was impaired by fatigue, drowsiness, alcohol, drugs, poor eyesight, etc.
- Driver was reckless, angry, emotional, or otherwise upset.
- □ Driver failed to turn lights on.
- Driver did not compensate for sun glare.
- □ Sunglasses worn at dusk or at night.
- Driver did not compensate for poor windshield wiper performance.

Vehicle Factors to Consider

- □ Truck's side marker lamp(s) not functional.
- □ Approaching vehicle's headlights not functional.
- □ Trailer not equipped with required lights and/or reflectors.
- □ Vehicle lights and/or reflectors dirty.
- Approaching vehicle's headlights misaligned, reducing visibility distance.
- Tractor's headlights misaligned causing approaching driver glare problem.
- □ Approaching vehicle brake failure or poor brake performance.
- Poor windshield wiper performance during inclement weather.
- Mechanical failure causing truck to stop before completing turn (engine stalled, spring brakes applied, drive train failed, etc.)

Highway and Environment Factors to Consider

- □ High accident rate history at location.
- □ Limited sight distance due to curve in road or hill crest.
- □ Speed limit or advisory speed too high.
- □ Lack of, improper, or confusing traffic control, signage, etc.
- □ Slippery road due to snow, ice or rain.
- □ Approaching driver's vision impaired by glare from headlights of opposing traffic.
- Reduced visibility due to precipitation, fog, sun glare, or low-light condition (night, dawn, or dusk).
- □ Truck inconspicuous because of background.